



Replacement Sheet for AIA # 10/718,352

Hybrid Automatic - Magnetic Isolator - Actuator  
By D. KENHOLZ, Filed 11/21/2003




Figure 1

REPLACEMENT SHEET FOR APP. # 10/718,352




Figure 2b





Figure 2a

REPLACEMENT SHEET FOR APA # 10 / 718,352



REPLACEMENT SHEET FOR APP. # 10 / 718,352




Figure 4

REPLACEMENT SHEET FOR APP. # 10 / 718,352





Figure 5

R E P L A C E M E N T   S H E E T   F O R   A P P . # 10 / 7 1 8 , 3 5 2



**Figure 6**




Figure 7

REPLACEMENT SHEET FOR APP. # 10/718,352